











instruction





1027 05 13 42
211/2



instruction



1027 05 13 42
211/2





++++ = MAX. 720°



++++ = MAX. 720°






instruction

1027 05 14 88
301/2




3

	M10	M12	M14	M16	M18	M
	35 Nm (26 ft.lbs)	50 Nm (37 ft.lbs)	80 Nm (59 ft.lbs)	120 Nm (89 ft.lbs)	165 Nm (122 ft.lbs)	 mm
	45 Nm (33 ft.lbs)	80 Nm (59 ft.lbs)	125 Nm (92 ft.lbs)	180 Nm (133 ft.lbs)	250 Nm (185 ft.lbs)	
	—	50 Nm (37 ft.lbs)	80 Nm (59 ft.lbs)	120 Nm (89 ft.lbs)	165 Nm (122 ft.lbs)	





AFST. / 1A




instruction

1027 05 14 88
301/2












3

	M10	M12	M14	M16	M18	M
	35 Nm (26 ft.lbs)	50 Nm (37 ft.lbs)	80 Nm (59 ft.lbs)	120 Nm (89 ft.lbs)	165 Nm (122 ft.lbs)	 mm
	45 Nm (33 ft.lbs)	80 Nm (59 ft.lbs)	125 Nm (92 ft.lbs)	180 Nm (133 ft.lbs)	250 Nm (185 ft.lbs)	
	—	50 Nm (37 ft.lbs)	80 Nm (59 ft.lbs)	120 Nm (89 ft.lbs)	165 Nm (122 ft.lbs)	



AFST. / 1A









instruction

1027 05 20 63
510

ONLY
FORD FOCUS / C-max



instruction

1027 05 20 63
510

ONLY
FORD FOCUS / C-max

